

Comberbach Play Area Inspection Sheet



Inspection Start: 30 April 2021 at 10:11

Inspected By: Steph

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Paths	No Hazard	—	—
Litter Bins	No Hazard	—	—
			—
Trees Visual	No Hazard	—	—
Shelter	No Hazard	—	—
Aerial zip Line	Needs Adjusting	Medium	Adjust
Grass mats coming up. Relay.			
Infant Play Unit	No Hazard	—	—
Infant Rocker 2	No Hazard	—	—
Junior Play Unit	Showing signs of weather	Low	Monitor
Upright posts and panels are now showing signs of weather and age. Monitor.			

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Safety Surfaces	No Hazard	—	—
Junior Swings	No Hazard	—	—
Perimeter Fences	No Hazard	—	—
Gates	Needs Adjusting	Low	Adjust
Grass Areas	No Hazard	—	—
Benches	—	—	—
Picnic benches need securing to ground. L brackets on memorial benches causing trip hazard.			
MUGA	No Hazard	—	—
Infant Swings	No Hazard	—	—
Infant Rocker 1	No Hazard	—	—

Comments:

Post around flower bed are starting to rot at the bottom. Monitor with view to replace.

Photo 1:



Photo 2:



Photo 3:



Photo 4:



Photo 5:



Photo 6:



Photo 7:



Photo 8:



Photo 9:





Northwich
town council

Authorised By:

Immediate Action:

Inspection
Completed:

Signature:

Addition
comments:

Location:

