

Comberbach Play Area Inspection Sheet



Inspection Start: 6 April 2022 at 11:06

Inspected By: Steph

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Paths	No Hazard	—	—
Litter Bins	No Hazard	—	—
			—
Trees Visual	No Hazard	—	—
Shelter	No Hazard	—	—
Aerial zip Line	No Hazard	—	—
Infant Play Unit	Showing signs of weather	Low	Monitor
And age. Monitor for signs of rot.			
Infant Rocker 2	No Hazard	—	—
Junior Play Unit	Showing signs of weather	Low	Monitor
And age. Monitor for signs of rot			

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Safety Surfaces	Cracks & Shrinkage	Low	Monitor
Junior Swings	Rope or Chain Wear	Medium	Replace
Replace d shackles on right hand side swing			
Perimeter Fences	No Hazard	—	—
Gates	—	—	—
Needs investigating			
Grass Areas	No Hazard	—	—
Benches	No Hazard	—	—
MUGA	—	—	—
Moss growth around outside. Remove and spray			
Infant Swings	No Hazard	—	—
Infant Rocker 1	No Hazard	—	—

Comments:

Hole in cobbles where bench has been removed. Repair

One pencil missing with stump left. Remove stump.

Multiple pencils rotting.

Photo 1:



Photo 2:



Photo 3:



Photo 4:



Photo 5:



Photo 6:



Photo 7:



Photo 8:





Northwich
town council

Authorised By:

Immediate Action:

Inspection
Completed:

Signature:

Addition
comments:

Location:

